


M e m o r a n d u m*Flex your power!
Be energy efficient!***To:** Jiwanjit Palaha – District 07
Project Manager**Date:** January 16, 2012**Attention:** Giap Hoang, Project Engineer**File:** 07-LA-10-PM 42.5
EA: 07-3X0101
Slope Stability Analysis**From:** DEPARTMENT OF TRANSPORTATION
DIVISION OF ENGINEERING SERVICES
Geotechnical Services
Office of Geotechnical Design South 1
Branch B**Subject:** Revised Geotechnical Investigation Report for 57-10 Interchange Cut Slope near Station 15+00

Per your request, the Office of Geotechnical Design South 1 (OGDS-1), Branch B has prepared this revised geotechnical investigation study report for slope stability analysis near the 57 and 10 Interchange. This revised report provides for an adjustment to the location identification of the analyzed slope from the original December 19, 2011. The adjusted slope location analyzed is near station 15+00 per the latest layout plans provided (Updated January 17, 2012). This is changed from the previous Station 9+00.

The purpose of this report is to summarize the results of our slope stability investigation and to provide recommendations for any additional work required to keep the slope in stable condition. This report follows a September 8, 2011 Slope Stability Evaluation Report for the buttress fill located north of this cut slope at PM 42.6.

2.0 SITE DESCRIPTION

The site is located east of the I-10 WB to SR-57 NB Connector facing the westerly direction. The slope is in a cut located at postmile 42.5 near I-10 WB to SR 57 NB Connector Alignment Station 15+00. The top of the slope being evaluated is approximately 250 feet above the ramp roadway grade. Based on measurements made in the field and cross sections provided to our office the slope is at a 1.7:1 grade within the bottom 100 feet and steepens to a 1.5:1 grade within 100 to 200 feet above the travel way elevation. At the present time, no distress was observed along the slope face or within the travel way at the toe of the slope. Photos of the cut slope are attached to this memo in Appendix A. A Vicinity Map is shown in Figure 1 below.



Vicinity Map – Figure 1

3.0 BACKGROUND

As discussed in the September 8th report, the buttress fill located about 300 feet to the north of this site had failed in February 2010. Subsequently, a portion of the slope was rebuilt at a 2:1 grade with a buttress fill. The slope face was covered by hydroseeding and erosion mats.

This site located about 300 feet to the south, was apparently undisturbed during the re-grading occurring to the north. However, upon completion of the grading process, the slope at this location was left slightly steeper than the surrounding grade. As mentioned previously, no distress has been observed at this location, however, as the steepest part of the cut slope along the 10 W/B to 57 N/B connector concern was raised about the stability.

4.0 GEOTECHNICAL INVESTIGATION

The geotechnical investigation for this project consisted of obtaining soil boring information from the investigation performed for the September 8th Report. From that investigation, two exploratory borings were drilled within the buttress repair area to the north. The borings, labeled as BH-1 and BH-2 were drilled along the slope face to depths of 55 feet and 48 feet, respectively. The borings from this buttress area were applied to the project area due to the similarity of the formational materials. The borings were advanced utilizing a mud rotary method with a CS 2000 drill rig for BH-1 and CS-1000 track mounted rig for BH-2. Both rigs were equipped with an automatic hammer. Boring locations were determined based upon field observations. The elevation of the boring locations is based on layout plans provided by District

Design. A third boring, BH-3, was performed to collect a bulk sample at the toe of the slope. Figure 2 included as an attachment shows the location of the borings.

4.1 Subsurface Conditions:

The Glendora Volcanics formation was encountered in the borings. The formation is a conglomerate with hard to very hard clasts of andesite ranging from gravel to boulder sized. The matrix is intensely weathered to decomposed tuff.

No ground water was encountered to the deepest depth of 55 ft. explored during drilling.

6.0 LABORATORY TESTING

Unconfined Compression test results were used to develop parameters for slope stability analysis. The test results were taken from the investigation used for the September 8th report. Unconfined compression results on the formational material, based on Test Method CTM 221 ranged from 1071 to 4728 psi. A lower value of 20 psi was also considered, however, that result was not used in the parameter evaluation due to its extremely lower result when compared to the other two results.

7.0 GEOLOGY

7.1 Regional Geology

The project site is located in the Transverse Ranges Geomorphic Province at the southern base of the San Jose Hills, north of the Puente Hills. The Transverse Ranges Province is characterized by east-west trending mountain ranges associated with east-west trending faults.

7.2 Site Geology

The slope failure and surrounding hillside have been mapped as the Glendora Volcanic Rocks – Volcanic Conglomerate (T.W. Dibblee, 2002). The conglomerate consists mainly of andesitic clasts ranging from an average of 1 to 12 inches in size, with blocks up to 6 feet. The conglomerate is poorly lithified. The matrix is highly tuffaceous, typically lapilli tuff (J.S. Shelton, 1955).

8.0 SEISMICITY

The nearest mapped fault is the San Jose Fault, which may have been exposed during the excavation for the buttress. The San Jose Fault is listed as a reverse fault dipping 25° to the north. The maximum magnitude of the San Jose Fault is 7.3. The site PGA was determined to be 0.5g.

8.1 Liquefaction Potential

The potential for liquefaction is estimated to be very low to negligible since the material is hard formational bedrock and also that ground water was not encountered in either boring.

9.0 SLOPE STABILITY ANALYSES

Slope stability analyses were performed using the Slope/W 2004 Version Program. The specific method for analysis used was the Morgenstern-Price Method due to its inclusion of both shear and inter-slice forces. This method provides a lower factor of safety than the Bishop's simplified method which ignores these inter-slice forces. The results of the slope stability analysis are included in Appendix B. The following table provides a summary of the unconfined compression results considered and strength parameters used for the analysis.

Table 1- Summary of Unconfined Compression Results

Boring	Sample/Depth	Material	qu (psi)
BH-1	S-1/0-5 ft	Sedimentary Rock – Conglomerate	20
BH-1	S-2/5-10 ft	Sedimentary Rock – Conglomerate	1071
BH-1	S-3/10-15 ft	Sedimentary Rock - Conglomerate	4728

Notes: Samples for S-2 and S-3 were less than 2 for the L/D ratio. Subsequently, the results were reduced by a proportional amount.

An average unconfined compression of the results for S-2 and S-3 was determined to be 1,790 psi. This result was used in the procedure for determining shear strength based on closely jointed rock masses (Hoek and Bray, 3rd Ed. 1992, pg 104). Using rock mass quality descriptions of moderately weathered and moderately fractured for sandstone type rock empirical constants were obtained to determine the shear strength (Hoek and Bray, 3rd Ed 1992, pg 108). Based on this analysis the resulting undrained shear strength used for slope stability analysis was 5,000 psf. The unit weight and friction angle used were 120 pcf and 0 degrees, respectively. The shear strengths were based on a depth and overburden pressure of 50 feet and 6000 psf, respectively.

Results of the analysis are shown in Appendix B as Figures B-1 and B-2. Figure B-1 shows the static case where the factor of safety is 1.86. Per the Bridge Design Specifications, BDS (April 2000, Section 4.4.9) the minimum factor of safety for static conditions is 1.5. Figure B-2 shows stability results under seismic conditions. Based on a PGA of 0.5g a pseudostatic coefficient of 0.2 was used in the analysis. The Factor of Safety generated was 1.22. the minimum factor of safety under seismic conditions should exceed 1.1.

10.0 DISCUSSION AND RECOMMENDATIONS

Based on our slope stability analysis, the slope at Station 15+00 appears to be stable for the present time. However, the following recommendations should be followed to help maintain the slope:

- 1) The slope should be monitored regularly for sign of distress and erosion. After periods of heavy rainfall the slope should be checked for signs of erosion or tension cracking.
- 2) An erosion cover such as an erosion control mat should be considered for application over the slope face. This will help prevent erosion gullies from forming after periods of heavy rainfall. The mat should extend to Station 15+00 from the latest Layout Plan Sheet.
- 3) In order to control rainfall runoff extending eastward the existing lower bench of the buttress along with the concrete v-ditch is also advisable. The lower bench should extend to Station 15+00 from the latest Layout Plan Sheet.

- 4) If you have any questions or comments, please call Sam Sukiasian at or 213-620-2135 or Kristopher Barker at 213-620-2334..


Prepared by:

Date: 1-17-12

Date: 1/17/12




KRISTOPHER BARKER, C.E.G.
Engineering Geologist
Office of Geotechnical Design – South 1
Branch B




SAM SUKIASIAN G.E.,
Senior Transportation Engineer
Office of Geotechnical Design – South 1
Branch B



cc: GS File room: gs_file_room @dot.ca.gov
GS Corporate: Shira Rajendra
Gustavo Ortega, OGDS1
District Materials Engineer
Planning: Steve Chan/D07CaltransCAGov



NOTES:
 1. SEE PLAN SHEET FOR CROSS SECTION LOCATION.
 2. SEE PLAN SHEET FOR BORING LOCATION.



NO.	DESCRIPTION	DATE	BY
1	ISSUED FOR PERMIT	10/15/00	J.M.
2	REVISED	11/15/00	J.M.
3	REVISED	12/15/00	J.M.
4	REVISED	01/15/01	J.M.
5	REVISED	02/15/01	J.M.
6	REVISED	03/15/01	J.M.
7	REVISED	04/15/01	J.M.
8	REVISED	05/15/01	J.M.
9	REVISED	06/15/01	J.M.
10	REVISED	07/15/01	J.M.
11	REVISED	08/15/01	J.M.
12	REVISED	09/15/01	J.M.
13	REVISED	10/15/01	J.M.
14	REVISED	11/15/01	J.M.
15	REVISED	12/15/01	J.M.
16	REVISED	01/15/02	J.M.
17	REVISED	02/15/02	J.M.
18	REVISED	03/15/02	J.M.
19	REVISED	04/15/02	J.M.
20	REVISED	05/15/02	J.M.
21	REVISED	06/15/02	J.M.
22	REVISED	07/15/02	J.M.
23	REVISED	08/15/02	J.M.
24	REVISED	09/15/02	J.M.
25	REVISED	10/15/02	J.M.
26	REVISED	11/15/02	J.M.
27	REVISED	12/15/02	J.M.
28	REVISED	01/15/03	J.M.
29	REVISED	02/15/03	J.M.
30	REVISED	03/15/03	J.M.
31	REVISED	04/15/03	J.M.
32	REVISED	05/15/03	J.M.
33	REVISED	06/15/03	J.M.
34	REVISED	07/15/03	J.M.
35	REVISED	08/15/03	J.M.
36	REVISED	09/15/03	J.M.
37	REVISED	10/15/03	J.M.
38	REVISED	11/15/03	J.M.
39	REVISED	12/15/03	J.M.
40	REVISED	01/15/04	J.M.
41	REVISED	02/15/04	J.M.
42	REVISED	03/15/04	J.M.
43	REVISED	04/15/04	J.M.
44	REVISED	05/15/04	J.M.
45	REVISED	06/15/04	J.M.
46	REVISED	07/15/04	J.M.
47	REVISED	08/15/04	J.M.
48	REVISED	09/15/04	J.M.
49	REVISED	10/15/04	J.M.
50	REVISED	11/15/04	J.M.
51	REVISED	12/15/04	J.M.
52	REVISED	01/15/05	J.M.
53	REVISED	02/15/05	J.M.
54	REVISED	03/15/05	J.M.
55	REVISED	04/15/05	J.M.
56	REVISED	05/15/05	J.M.
57	REVISED	06/15/05	J.M.
58	REVISED	07/15/05	J.M.
59	REVISED	08/15/05	J.M.
60	REVISED	09/15/05	J.M.
61	REVISED	10/15/05	J.M.
62	REVISED	11/15/05	J.M.
63	REVISED	12/15/05	J.M.
64	REVISED	01/15/06	J.M.
65	REVISED	02/15/06	J.M.
66	REVISED	03/15/06	J.M.
67	REVISED	04/15/06	J.M.
68	REVISED	05/15/06	J.M.
69	REVISED	06/15/06	J.M.
70	REVISED	07/15/06	J.M.
71	REVISED	08/15/06	J.M.
72	REVISED	09/15/06	J.M.
73	REVISED	10/15/06	J.M.
74	REVISED	11/15/06	J.M.
75	REVISED	12/15/06	J.M.
76	REVISED	01/15/07	J.M.
77	REVISED	02/15/07	J.M.
78	REVISED	03/15/07	J.M.
79	REVISED	04/15/07	J.M.
80	REVISED	05/15/07	J.M.
81	REVISED	06/15/07	J.M.
82	REVISED	07/15/07	J.M.
83	REVISED	08/15/07	J.M.
84	REVISED	09/15/07	J.M.
85	REVISED	10/15/07	J.M.
86	REVISED	11/15/07	J.M.
87	REVISED	12/15/07	J.M.
88	REVISED	01/15/08	J.M.
89	REVISED	02/15/08	J.M.
90	REVISED	03/15/08	J.M.
91	REVISED	04/15/08	J.M.
92	REVISED	05/15/08	J.M.
93	REVISED	06/15/08	J.M.
94	REVISED	07/15/08	J.M.
95	REVISED	08/15/08	J.M.
96	REVISED	09/15/08	J.M.
97	REVISED	10/15/08	J.M.
98	REVISED	11/15/08	J.M.
99	REVISED	12/15/08	J.M.
100	REVISED	01/15/09	J.M.
101	REVISED	02/15/09	J.M.
102	REVISED	03/15/09	J.M.
103	REVISED	04/15/09	J.M.
104	REVISED	05/15/09	J.M.
105	REVISED	06/15/09	J.M.
106	REVISED	07/15/09	J.M.
107	REVISED	08/15/09	J.M.
108	REVISED	09/15/09	J.M.
109	REVISED	10/15/09	J.M.
110	REVISED	11/15/09	J.M.
111	REVISED	12/15/09	J.M.
112	REVISED	01/15/10	J.M.
113	REVISED	02/15/10	J.M.
114	REVISED	03/15/10	J.M.
115	REVISED	04/15/10	J.M.
116	REVISED	05/15/10	J.M.
117	REVISED	06/15/10	J.M.
118	REVISED	07/15/10	J.M.
119	REVISED	08/15/10	J.M.
120	REVISED	09/15/10	J.M.
121	REVISED	10/15/10	J.M.
122	REVISED	11/15/10	J.M.
123	REVISED	12/15/10	J.M.
124	REVISED	01/15/11	J.M.
125	REVISED	02/15/11	J.M.
126	REVISED	03/15/11	J.M.
127	REVISED	04/15/11	J.M.
128	REVISED	05/15/11	J.M.
129	REVISED	06/15/11	J.M.
130	REVISED	07/15/11	J.M.
131	REVISED	08/15/11	J.M.
132	REVISED	09/15/11	J.M.
133	REVISED	10/15/11	J.M.
134	REVISED	11/15/11	J.M.
135	REVISED	12/15/11	J.M.
136	REVISED	01/15/12	J.M.
137	REVISED	02/15/12	J.M.
138	REVISED	03/15/12	J.M.
139	REVISED	04/15/12	J.M.
140	REVISED	05/15/12	J.M.
141	REVISED	06/15/12	J.M.
142	REVISED	07/15/12	J.M.
143	REVISED	08/15/12	J.M.
144	REVISED	09/15/12	J.M.
145	REVISED	10/15/12	J.M.
146	REVISED	11/15/12	J.M.
147	REVISED	12/15/12	J.M.
148	REVISED	01/15/13	J.M.
149	REVISED	02/15/13	J.M.
150	REVISED	03/15/13	J.M.
151	REVISED	04/15/13	J.M.
152	REVISED	05/15/13	J.M.
153	REVISED	06/15/13	J.M.
154	REVISED	07/15/13	J.M.
155	REVISED	08/15/13	J.M.
156	REVISED	09/15/13	J.M.
157	REVISED	10/15/13	J.M.
158	REVISED	11/15/13	J.M.
159	REVISED	12/15/13	J.M.
160	REVISED	01/15/14	J.M.
161	REVISED	02/15/14	J.M.
162	REVISED	03/15/14	J.M.
163	REVISED	04/15/14	J.M.
164	REVISED	05/15/14	J.M.
165	REVISED	06/15/14	J.M.
166	REVISED	07/15/14	J.M.
167	REVISED	08/15/14	J.M.
168	REVISED	09/15/14	J.M.
169	REVISED	10/15/14	J.M.
170	REVISED	11/15/14	J.M.
171	REVISED	12/15/14	J.M.
172	REVISED	01/15/15	J.M.
173	REVISED	02/15/15	J.M.
174	REVISED	03/15/15	J.M.
175	REVISED	04/15/15	J.M.
176	REVISED	05/15/15	J.M.
177	REVISED	06/15/15	J.M.
178	REVISED	07/15/15	J.M.
179	REVISED	08/15/15	J.M.
180	REVISED	09/15/15	J.M.
181	REVISED	10/15/15	J.M.
182	REVISED	11/15/15	J.M.
183	REVISED	12/15/15	J.M.
184	REVISED	01/15/16	J.M.
185	REVISED	02/15/16	J.M.
186	REVISED	03/15/16	J.M.
187	REVISED	04/15/16	J.M.
188	REVISED	05/15/16	J.M.
189	REVISED	06/15/16	J.M.
190	REVISED	07/15/16	J.M.
191	REVISED	08/15/16	J.M.
192	REVISED	09/15/16	J.M.
193	REVISED	10/15/16	J.M.
194	REVISED	11/15/16	J.M.
195	REVISED	12/15/16	J.M.
196	REVISED	01/15/17	J.M.
197	REVISED	02/15/17	J.M.
198	REVISED	03/15/17	J.M.
199	REVISED	04/15/17	J.M.
200	REVISED	05/15/17	J.M.

LAYOUT
 SCALE 1:500 L-2

Boring Location Plan- Figure 2

APPENDIX A
Site Photos




Photo 1 – View of Slope from Northwest




Photo 2 – View of Slope from West




Photo 3 – View of Slope from North

APPENDIX B
Slope Stability Analysis

EA 07-3X0101
 57-10 Slope near Station 15+00
 Sandstone - Conglomerate
 Su = 5,000 psf for a 200 foot
 High Slope at a 1.5 to 1.7 grade.

④ 1.861

Case: Static




Figure A-1

EA 07-3X0101
57-10 Slope near Station 15+00
Sandstone - Conglomerate
Su = 5,000 psf for a 200 foot
High Slope at a 1.5 to 1.7 grade.

Case: Seismic

1.221




Figure A-2