


SR 29 / SR 281 INTERSECTION OPTIONS

SIGNALIZED INTERSECTION




- The 2007 signal is performing well at the existing SR 29/ SR 281 intersection. Consequently this has eliminated the need for additional traffic control at the intersection.
- A Value Analysis (VA) team evaluated the performance and cost saving improvements recommended in the VA Report, dated November 5, 2008, to eliminate the interchange options. The following interchange options have been eliminated from further consideration:


INTERCHANGE OPTIONS ELIMINATED:



Diamond with State Route 29 frontage road access.



Partial cloverleaf with State Route 29 frontage road access.



Diamond with Red Hills Road frontage road access.



Partial cloverleaf with Red Hills Road frontage road access.